Monday, 6/19/2006 11:24:55 AM Kim Johnston User: **Process Sheet** : FLOAT SKIDTUBE : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 27611 : 10366 **Estimate Number** : D412742013 **Part Number** : NIA P.O. Number S.O. No. : NIA : N/A **Drawing Number** : 6/19/2006 This Issue : N/A Prsht Rev. **Project Number** : NA : LANDING GEAR : N/A Type **Drawing Revision** First Issue AIM: : 27610 Material **Previous Run** : 7/20/2006 Qty: 1 Um: Each **Due Date** Written By Checked & Approved By New Issue KJ/JLM Comment Est Rev:B 06-06-08 As per DSI9336 JLM **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL Photocopy bluefile and create labels per PPP D412-742-013 &DSI 9330 & DSI 9336 CHG001 FLOAT SKID ASSEMBLY 2.0 27611A Comment: Sub-Component FLOAT SKID ASSEMBLY D2571 1.0000 Each(s)/Unit 1.0000 Each(s) Comment: Qty.: Total: Pick: **Qty Part Number** Description Batch Saddle Fwd Outside D2572 Saddle, Fwd, In 4.0 1.0000 Each(s)/Unit Comment: Qty.: Total: 1.0000 Each(s) Pick: Qty Part Number Description D2572 Saddle Fwd Inside 5.0 D2573

Page 1

Comment: Qty.:

Pick:

Qty Part Number

1 D2573

1.0000 Each(s)/Unit

Total:

Description

Saddle Aft Outside

1.0000 Each(s)

Batch

Dant	erospace	Liu							
W/O:			W	ORK ORDER CHANGES					
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
NCR:		\	NORK ORD	ER NON-CONFORMAN	CE (NCF	₹)			
		Description of NC		Corrective Action Section B	-	Vorifi	ication	Approval	Approval
DATE	STEP	Section A	Initial	Action Description	Sign 8	9	tion C	Approval Design Mgr	Approval QC Inspector

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B		Verification	Annessal	Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	QC Inspector			
	-			•							
		,									

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	1/C C	losed:	Date:

Monday, 6/19/2006 11:24:55 AM Date: 4 User: Kim Johnston **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 27611 Job Number: Description: Seq. #: Machine Or Operation: D2574 Saddle, Aft, In 6.0 1.0000 Each(s)/Unit Total: Comment: Qty.: 1.0000 Each(s) Pick: **Qty Part Number** Description Saddle Aft Outside D2574 D2747 7.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Description Aty Part Number 4 D2747 Saddle Spaces 8.0 D2876 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2876 Saddle Spacer Saddle Spacer D2877 9.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch 2 D2877 Saddle Spacer D34031 10.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** Bushing /> 16 D3403-1 D34033 11.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description **Qty Part Number** Bushing_ D3403-3

Dan A	erospac	e Lta							
W/O:			WC	RK ORDER CHANGES	3				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCR)			
DATE	eten.	Description of NC		Corrective Action Section B		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date		ion C	Approval Design Mgr	QC Inspector

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	1/C C	osed:	Date:

Monday, 6/19/2006 11:24:55 AM Date: . User: Kim Johnston **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 27611 Job Number: Seq. #: Description: **Machine Or Operation:** D3405041 Lug Assembly 12.0 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: Pick: Description Batch **Qty Part Number** B26514 GHW Lug ✓ 1 D3405-041 D3405043 Lug Assembly 13.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Qty Part Number Description GHW Lug 1 D3405-043 AN4C6A 14.0 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Qty Part Number Description_e W100651 16 AN4C6A BOLT AN4C46A 15.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: **Qty Part Number** Description Batch 4 AN4C46A AN4C52A 16.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 8 AN4C52A Bolt AN6C12A 17.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 8 AN6C12A Bolt

W/O:			WOF	RK ORDER CHANGES	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
DATE	STEP	PR	OCEDURE CHAN	GE	Ву	Date Qt	Approval Mfg / Design Mgr	Approval QC Inspector
NCR:	·		WORK ORDE	R NON-CONFORMAN	CE (NCR)		
				Corrective Action Section B		-		<u> </u>
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C	n Approval Design Mgr	Approval QC Inspector
								-
				•				
Part No	o:	PAR #:	Fault Category:	NCR: \	'es No	DQA:	Date:	
NOTE: D	iate & initi:	al all entries			A. NIC CL	sead:	Dato	

Date: > User: Job Number:

Monday, 6/19/2006 11:24:55 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

Job Number: 27611

Part Number: D412742013



Seq. #:

Machine Or Operation:

Description:

18.0

AN960C416L

WASHER



Comment: Qty.:

32.0000 Each(s)/Unit Total:

32.0000 Each(s)

Pick:

Qty Part Number ✓32 AN960C416L Description

Washer__ 10 / 0.0 65/

19.0

AN960C616L

WASHER





Comment: Qty.:

8.0000 Each(s)/Unit Total:

8.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

M18822 8 AN960C616L Washer

20.0

AN960C716L

WASHER



Comment: Qty.: 16.0000 Each(s)/Unit Total:

16.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 AN960C716L

Washer M101579 ~

21.0

MS210434

Nut





Comment: Qty.:

29.0000 Each(s)/Unit Total:

29.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

29 MS21043-4Nut 1015/396 ~

- 22.0

NAS1515H4L

Inventory



Comment: Qty.:

32.0000 Each(s)/Unit Total:

Pick:

32.0000 Each(s)

Qty Part Number 32 NAS1515H4L Description

Washer

M103854 25MG 7 PASINFOU M18918 7MG > S.RHI -

Dart A	\erospa	ce Ltd							
W/O:			WO	RK ORDER CHANGES	3				
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
NCR:		V	ORK ORDE	ER NON-CONFORMAN	CE (NCR	2)			
		Description of NC		Corrective Action Section B		Vorifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date		ion C	Design Mgr	Approval QC Inspector
		·							
*									

Part No:	PAR #:	Fault Category:	NCR:	Yes No	DQA:	Date:
NOTE: Date & initial all entries				QA: N/C	Closed:	Date:

Monday, 6/19/2006 11:24:55 AM Date: \ User: Kim Johnston. **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 27611 Part Number: D412742013 Job Number: Seq. #: Description: **Machine Or Operation:** NAS1515H6L Inventory 23.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description Qty Part Number Batch Washer 118918/ NAS1515H6L 24.0 NAS1515H7L Inventory Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description Batch Qty Part Number 16 NAS1515H7L M100727 Washer 25.0 D3407041 Tow Ring Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description **Qty Part Number** D3407-041 **TOW RING** 26.0 D34173 Washer Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch 2 WASHER D3417-3 27.0 D34561 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch 151×701~ D3456-1 WASHER

Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector				

NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Approval	A			
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Design Mgr	Approval QC Inspector			
								•			
		,									

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: I	N/C C	losed:	Date:

Monday, 6/19/2006 11:24:56 AM Date: . Ųser: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 27611 Job Number: **Description:** Seq. #: **Machine Or Operation:** AN4C7A 28.0 4.0000 Each(s) Comment: Qty.: 4.0000 Each(s)/Unit Total: Bolt ✓ Batch: INSPECT 100% KITS FOR COMPLETENES QC4 29.0 c206/10/051 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING 1 PACKAGING RESOURCE #1 30.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-013 DOCUMENT CONTROL 31.0 DC Comment: DOCUMENT CONTROL U do. 10.05 Inspection Level 21 Job Completion

Dart	Aeros	pace L	₋td
------	-------	--------	-----

W/O:		WORK ORDER CHANGE	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector					
						•						
·												
					<u> </u>							

NCR:	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			A	Ammunual	
DATE	STEP	Section A	Initial Design Mgr	Initial Action Description Sign &		Verification Section C	Approval Design Mgr	Approval QC Inspector	
								Ŋ.	
					<u>.</u>				

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	1/C C	osed:	Date:

06-06-19 PH

NIA

1 Um:

Each

: FLOAT SKID ASSEMBLY

: D412742043

: N/A

: DE

:NIA

: 7/20/2006

: D3391 REVIO

Monday, 6/19/2006 11:25:10 AM

User:

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 27611A

Estimate Number

: 10756

P.O. Number

AIH:

This Issue

: 6/19/2006

Prsht Rev.

First Issue **Previous Run**

: NIA : 27610A

Written By

Checked & Approved By

Comment

: Est Rev A 95.10.13

Type

S.O. No. : NIA

ECN 773 dwg @ rev.D Est Rev B 06.02.13

: LANDING GEAR

New Issue

EC

KJ/JLM

Material

Due Date

Drawing Name

Part Number

Drawing Number

Project Number

Drawing Revision

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

DOCUMENT CONTROL

1.0

DC

Comment: DOCUMENT CONTROL

If D412-742-043 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-742-043 CHG001

Total:

D25775 2.0



Comment: Qty.:

1.0000 Each(s)/Unit

Qty 1 D2577-5

Part Number Description Wearplate Batch B24199

3.0

D3391021

pick:

Fwd Tube Assembly

Wearplate, Centre

1.0000 Each(s)



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

pick:

Qty Part Number Description

D3391-021 Fwd Tube Assembly

Batch

4.0

D3391023

Mid Tube Assembly



1.0000 Each(s)/Unit Total: 1.0000 Each(s)

pick:

Comment: Qty.:

Part Number Description

D3391-023 Mid Tube Assembly

DL 06/08/25

W/O:			WOF	RK ORDER CHANGES					
DATE	STEP	PR	OCEDURE CHAN	GE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
						· · · · · · · · · · · · · · · · · · ·			
NCR:			WORK ORDE	R NON-CONFORMANO	CE (NCE	2)			
NCK:			Corrective Action Continue						
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description Design Mgr	Sign 8		cation ion C	Approval Design Mgr	Approval QC Inspector
					-				
				•					
		,							
									-
Part No):	PAR #:	Fault Category:	NCR: Y	es No	DQA:		Date:	
	ate & initial a				A: N/C CI				

Monday, 6/19/2006 11:25:10 AM Date: User: Kim Johnston **Process Sheet Drawing Name: FLOAT SKID ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 27611A Job Number: Seq. #: **Machine Or Operation: Description:** 5.0 D3391025 Aft Tube Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description D3391-025 Aft Tube Assembly B26578 D34601 WEARPLATE 6.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: pick: Qty Part Number Description Batch Wearplate BZ4622 D3460-1 WEARPLATE 7.0 D34603 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) check Inv. pick: Qty Part Number Description Batch B25443 BOLT 1 D3460-3 Wearplate AN3C4A 8.0 Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) pick: Qty Part Number Description Batch m101390 AN3C4A Bolt 9.0 AN3C6A Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) pick: FC 06 08 28 Description Batch Qty Part Number m101291 Bolt 12 AN3C6A

Dart A	erospa	ce Ltd							
W/O:		· · · · · · · · · · · · · · · · · · ·	WO	RK ORDER CHANGES	3	***************************************	<u>,,</u>		
DATE	STEP	PRO	OCEDURE CHAP	NGE	Ву	Date	e Qty	Approval Mfg / Design Mgr	Approval QC Inspector
NCR:		•	WORK ORDE	ER NON-CONFORMAN	CE (NCR	()			
DATE	STEP	Description of NC	Initial	Sign &	Verification Section C		Approval Design Mgr	Approval QC Inspector	
		Section A	Design Mgr	Action Description Design Mgr	Date	Sect	ion C	Design Mgi	QC inspector
	,								
			,						

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA :	Date:
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Monday, 6/19/2006 11:25:10 AM Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 27611A Job Number: Description: Seq. #: Machine Or Operation: BOLT AN3C7A 10.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) pick: Part Number Description Batch Qty AN3C7A 8 Bolt AN960C10L 11.0 Total: 44.0000 Each(s) Comment: Qty.: 44.0000 Each(s)/Unit pick: Part Number Description Batch Qty AN960C10L Washer _____00 186 WASHER 12.0 NAS1515H3L 44.0000 Each(s) Comment: Qty.: 44.0000 Each(s)/Unit Total: FC 06 08 28 pick: Qty Part Number Description Batch migoad NAS1515H3L Washer HAND FINISHING RESOURCE #1 13.0 Comment: HAND FINISHING RESOURCE #1 1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391 06-08-31 LPS-3 m10/092 9... 2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment. using 7/16" "T" Pins. Sikaflex-241/-291 M 101 953 A/R Expiry date: 10/04 3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon". Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex. LPS Procyon M17168 A/R Sikaflex-241/-29,1 _____/01953 A/R 10/04 Expiry date: 4-Remove "T" pins once sikaflex is dry. pl 04/08/38

W/O:		WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
-							

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	Verification	Annuaral		
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector
						-		
								ż
							·	

Part No:	PAR #:	Fault Category:	NCR:	Yes (No) DQA:	Date: 06/09/12
NOTE: Date & initial all entries	,			QA: N/C Closed:	Date:

Monday, 6/19/2006 11:25:11 AM Date: Kim Johnston User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FLOAT SKID ASSEMBLY Part Number: D412742043 Job Number: 27611A Job Number: Seq. #: **Machine Or Operation:** Description: 5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser. 04/08/31 QC5 INSPECT WORK TO CURRENT STEP 14.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 PACKAGING 1 15.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 Location:_ PPP Rev: DOCUMENT CONTROL 16.0 DC W Dlashell! Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

W/O:			WOF	RK ORDER CHANGES					
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
			WORK OPNE	D NON CONFORMANC	E (NCE	<u> </u>			
NCR:				R NON-CONFORMANC	E (NCP	·)		·	
DATE	STEP	Description of NC	Initial	Corrective Action Section B	Sign 8	Verification		Approval	Approval
		Section A	Design Mgr	Action Description Design Mgr	Date	Sect	Section C	Design Mgr	QC Inspector
				4			,		
1									
Part No):	PAR #:	Fault Category:	NCR: Y	es No	DQA:		Date:	
NOTE: D	ata & initia	l all entries			A: N/C CI				

H:\forms\Quality Assurance\approved forms\NCRWO revC









